

Werner, Robert

From: Werner, Robert
Sent: Friday, July 12, 2013 9:02 AM
To: 'mailto:Richard.Beauchamp@dshs.state.tx.us'
Cc: Miller, Garyg
Subject: FW: San Jacinto River Waste Pits
Attachments: Letter - MegaSand Enterprises, Inc. - 104(e) - 2011-07-11 Response received at EPA (SDMS#637980).pdf; Letter - Houston International Terminal, Inc. - 104(e) Ltr - 2010-09-27 Response received at EPA (SDMS #610644).pdf

Mr. Beauchamp

Attachment B in the first attached letter from MegaSand Enterprises, Inc. (MEI) identifies names of customers that purchased sand that MEI dredged from the "sand mining operation at the SJRWP Site."

Attachment A in the same letter to view Mega's illustrates:

1. Boundary lines of the area from which MEI claims that have dredged sand and clay.
2. Boundary lines of CPT (b) (6) plant site upon which MEI claims that have temporarily placed clay dredged from the dredge area.
3. Boundary lines of the Spoils Mitigation Area MEI claims to have deposited clay, i.e., overburden, from sand dredging activities.
4. CPT (b) (6) plant site is on the west side of the Spoils Mitigation Area.
5. The twenty acre land area upon which McGinnes Industrial Maintenance Corporation had disposed sludge from a paper mill is on the east side of the Spoils Mitigation Area.

During a March 8, 2008, conversation I'd had with CPT (b) (6) I'd understood him to say that he was selling (or maybe he said he'd already sold) 720,000 tons of sand to a construction company that was working on I-10. I'd not asked him for the name of the construction company.

Please call me if you have further questions.

Bob Werner
 Enforcement Officer
 U.S.E.P.A.
 214.665.6724

From: Miller, Garyg
Sent: Wednesday, July 10, 2013 12:54 PM
To: Werner, Robert
Subject: FW: San Jacinto River Waste Pits

Thanks Bob

Gary Miller
 EPA Remedial Project Manager
 214-665-8318
miller.garyg@epa.gov

From: Beauchamp, Richard (DSHS) [<mailto:Richard.Beauchamp@dshs.state.tx.us>]
Sent: Tuesday, July 09, 2013 11:27 AM
To: Miller, Gary
Subject: San Jacinto River Waste Pits

Gary,

I need to get some follow-up info on the **sand mining operation at the SJRWP Site** for a report back to the ATSDR regarding the status of the recommendations we made in our health assessment document. In the report (page 51 of the PHA document), we recommended that, "Efforts should be made to determine greater details of the sand mining operation, including when sands were mined from the area adjacent to the pits with respect to when wastes were disposed of in the pits, where mined sands have been distributed, and if possible, obtain sand samples for dioxin measurements."

Thank you,
Richard B.

Richard A. Beauchamp, M.D.
Senior Medical Toxicologist
Health Assessment & Toxicology Program
Environmental & Injury Epidemiology & Toxicology Unit
Texas Department of State Health Services
1100 West 49th Street
PO Box 149347, MC1964
Austin, TX 78714-9347

E-mail Richard.Beauchamp@dshs.state.tx.us
Phone (512) 458-7111 Ext. 6434
Phone (512) 776-6434
FAX (512) 458-7776

*****Confidentiality Notice*****

The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your computer system.

Thank you.